



## education

Department:
Education
REPUBLIC OF SOUTH AFRICA

T680(E)(M29)T APRIL 2010

NATIONAL CERTIFICATE

## **ENGINEERING DRAWING N2**

(8090272)

29 March (X-Paper) 09:00 - 13:00

This question paper consists of 4 pages and 6 annexures.

# DEPARTMENT OF EDUCATION REPUBLIC OF SOUTH AFRICA

NATIONAL CERTIFICATE ENGINEERING DRAWING N2 TIME: 4 HOURS MARKS: 100

#### **INSTRUCTIONS AND INFORMATION**

- 1. Answer ALL the questions.
- 2. Read ALL the questions carefully.
- 3. Number the answers correctly according to the numbering system used in this question paper.
- 4. Write neatly and legibly.

#### QUESTION 1: WELDING, COMPUTER-AIDED DRAUGHTING FASTERNERS AND ELECTRICAL FITTINGS

1.1	Name FIVE types of storage devices when using computer-aided draughting.		
1.2	Name the sketch of the stud in FIGURE 1, ANNEXURE A (attached). Write the answer next to the question number (1.2.1 - 1.2.5) in the ANSWER BOOK.		
1.3	Name the FOUR main parts of a welding symbol.		
1.4	Give the abbreviations of the following terms:		
	1.4.1 1.4.2 1.4.3	Pitch circle diameter Chamfer Countersunk	(1) (1) (1)
1.5	What is	the main material that electrical fittings are made of?	(1) <b>[18]</b>

#### **QUESTION 2: SCREW THREADS**

Draw, to scale 1:1, an M50  $\times$  5 mm pitch, a single-start, external right-hand V-screw thread with a length of 80 mm to fit the bolt in FIGURE 2, ANNEXURE B (attached). The screw thread and bolt must be in a horizontal position.

[12]

#### QUESTION 3: FIRST-ANGLE ORTHOGRAPHIC PROJECTION

FIGURE 3, ANNEXURE C (attached) shows two views of a pipe clamp in first-angle orthographic projection.

The front elevation is a half selection view with the right half in section. The left view is an outside view. The M20 nuts have been omitted.

Draw, to scale 1:2 (half scale) and in first-angle orthographic projection, the following views with M20 nuts in position:

3.1	A full sectional front view on cutting plane N-N	(7)
3.2	A full sectional left view on cutting plane M-M	(7)
3.3	Insert SIX dimensions	(3)
3.4	Draw the first-angle orthographic projection symbol in a space below the title and scale	(1)
3.5	Draw the following title and scale centrally beneath the layout:	
	Pipe clamp Scale 1:2	(2)

#### **QUESTION 4: ISOMETRIC**

FIGURE 4, ANNEXURE D (attached) shows two views of a work piece in first-angle orthographic projection.

Do NOT draw the given views but draw to scale 1:1 an isometric view of the work piece.

Point B must be the lowest point.

No hidden detail is required.

[15]

[20]

#### **QUESTION 5: INTERPENETRATION**

FIGURE 5, ANNEXURE E (attached) shows in first-angle orthographic projection an incomplete front view and top view of a T-end.

5.1 Draw the TWO given views to full scale (1:1). (2)
5.2 Complete the front view by plotting the curve of interpenetration. (6)
5.3 ALL projection and construction lines are to be shown. (2)
[10]

## QUESTION 6: THIRD-ANGLE ORTHOGRAPHIC PROJECTION AND MACHINE SYMBOLS

FIGURE 6, ANNEXURE F (attached) shows an outside front elevation and an outside right view of a model.

Draw, to scale 1:1 (full scale), the following views of the model:

	TOTAL:	100
6.6	Insert the third-angle orthographic projection symbol in a space beneath the layout	(1) <b>[25]</b>
6.5	Add the title and scale centrally beneath the layout	(2)
6.4	Add any SIX dimensions	(3)
6.3	An outside right view	(5)
6.2	A full sectional top view on cutting plane Z-Z	(8)
6.1	A full sectional front view on cutting plane Y-Y	(6)

## ANNEXURE A




FIGURE 1

## ANNEXURE B




FIGURE 2

## ANNEXURE C




FIGURE 3




FIGURE 4

## ANNEXURE E




FIGURE 5

### ANNEXURE F




FIGURE 6